

BOOK 258 PAGE 58  
MECKLENBURG COUNTY HEALTH DEPARTMENT  
BOYDTON, VIRGINIA

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

August 3, 1976

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Clarksville, Virginia 23927

Dear Mr. Wilson:

On July 28, 1976, a soil evaluation of Merifield Acres, Roanoke Point, Unit 6, consisting of 39 lots, was completed by Wayne Lenhart, Sanitarian, and me.

Lots 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, and 39 are each considered suitable for septic tank and drainfields for one single family dwelling unit (up to three bedrooms) with individual water supplies.

Lot 28 is to be limited to a dwelling unit of no more than two bedrooms.

In some instances, due to the degree of slope and depending on the location of the dwelling unit, pumping of the septic tank effluent to the drainfield may be required.

This approval is based upon the necessity of the septic tank and drainfield systems being located by the Mecklenburg County Health Department prior to construction. Therefore, we recommend that each buyer contact this office before construction is started.

Also, local ordinance requires that a Building Permit be obtained from the Office of the Building Inspector before construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

c.c.: Mecklenburg County Administrator

MECKLENBURG COUNTY HEALTH DEPARTMENT

BOYDTON, VIRGINIA 23917

November 16, 1976

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Clarksville, Virginia 23927

Dear Mr. Wilson:

On November 8, 1976, a soil evaluation of Merifield Acres, Unit 7, Section A, was completed by Wayne Lenhart, Sanitarian, Mecklenburg County Health Department, and me.

The following lots are considered suitable for septic tanks and drainfields for individual dwelling units up to three (3) bedrooms with an individual water supply per lot:

Unit 7, Section A - Lots 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 18, 19, and 20.

Due to the location of surrounding wells and soils which are shallow to rock, lot 17 is not considered suitable for the installation of a septic tank and drainfield system.

This approval is based upon the necessity of the septic tank and drainfield systems being located by the Mecklenburg County Health Department prior to construction. Therefore, we recommend that each buyer contact this office before construction is started.

Also, local ordinance requires that a Building Permit be obtained from the Office of the Building Inspector before construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

c.c.: Mecklenburg County Administrator

MECKLENBURG COUNTY HEALTH DEPARTMENT

BOYDTON, VIRGINIA 23917

December 21, 1976

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Clarksville, Virginia 23927

Dear Mr. Wilson:

On December 16, 1976, a soil evaluation of the lots in Merifield Acres, Unit 7, Sections B and C, was completed by Wayne Lenhart, Sanitarian, Mecklenburg County Health Department, and me. The results of the evaluation are as follows:

Unit 7, Section B - Lots 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, and 38 are considered suitable for the installation of septic tank and drainfield systems for single family dwelling units with an individual water supply per lot.

Unit 7, Section C - Lots 39, 40, 41, 43, 44, 45, 46, 49, 50, 51, 52, 53, 54, and 55 are considered suitable for the installation of septic tank and drainfield systems for single family dwelling units with an individual water supply per lot.

Lot 42 is not considered suitable because the location of drainfield sites on adjacent lots does not leave enough area for minimum distances between well and drainfield to be maintained.

Lots 47 and 48 are not considered suitable for the installation of a drainfield system because of unacceptable soil characteristics (shallow to rock).

Also, it should be noted that some lots, depending on house location may require a pumping system to get the effluent from the septic tank to the drainfield.

The above approvals are based upon the necessity of the septic tank and drainfield systems being located by the Mecklenburg County Health Department prior to construction. Therefore, we recommend that each buyer contact this office before construction is started.

Local ordinance requires that a Building Permit be obtained from the Office of the Building Inspector before construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

c.c.: Mr. B. D. McCauley, Mecklenburg County Administrator

MECKLENBURG COUNTY HEALTH DEPARTMENT

BOYDTON, VIRGINIA 23917

March 15, 1977

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Clarksville, Virginia 23927

Dear Mr. Wilson:

Based on the revised plat submitted on March 11, 1977, a re-evaluation of Merifield Acres, Unit 7, Section C, Lots 45, 46, 47, 48, and 49, is as follows:

A portion of the original lot 46 has been combined with lot 47 to form a new lot 46, which is now considered suitable for the installation of a septic tank and drainfield.


The original lots 48 and 49 have been combined to form a new lot 49, which is now considered to be suitable for the installation of a septic tank and drainfield.

This approval is for a single family dwelling unit, per lot, with an individual water supply. Also, it should be noted that, depending on house location, a pumping system may be required to get the effluent from the septic tank to the drainfield.

The above approvals are based upon the necessity of the septic tank and drainfield systems being located by the Mecklenburg County Health Department prior to construction.

Local ordinance requires that a Building Permit be obtained from the Office of the Building Inspector before construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

c.c.: Mr. B. D. McCauley, Mecklenburg County Administrator

MECKLENBURG COUNTY HEALTH DEPARTMENT  
BOYDTON, VIRGINIA

April 7, 1977

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Clarksville, Virginia 23927

Dear Mr. Wilson:

On April 7, 1977, a soil evaluation of Merifield Acres, Unit 7, Section D, was completed by Wayne Lenhart, Sanitarian, Mecklenburg County Health Department, and me. The results of that evaluation are as follows:

Lots 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 113, 114, 115, 116, 117, 118, 119, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, and 135 are considered suitable for the installation of a septic tank and subsurface drainfield system for single family dwelling units (up to three (3) bedrooms) with individual water supplies per lot.

Lots 105, 112, and 120 are considered suitable for a drainfield system to serve single family dwelling units of no more than two (2) bedrooms with individual water supplies on each lot.

Per your request, and based on a revised plat submitted April 7, 1977, the following shall apply:

Lots 106 and 107 are to be combined to form a single building site-lot 106A which is suitable for a dwelling unit of no more than three (3) bedrooms

Lots 108 and 109 are to be combined to form one building site-Lot 108A, and lots 110 and 111 are to be combined to form one building site-111A. These two lots, 108A and 111A, are considered suitable for dwelling units of no more than two (2) bedrooms per lot.

Lot 56 is not considered suitable for a septic tank and drainfield system due to insufficient room to maintain minimum distances between the wells on adjacent lots as required by State Law.

Due to the position in the landscape, heavy clay subsoils, and a seasonal high water table, lots 136 and 137 are not considered suitable for the installation of subsurface drainfield sewage disposal systems.

Also, it should be noted that, depending on the house location, some lots may require a pumping system to get the effluent from the septic tank to the designated drainfield area.

Mr. David Wilson


-2-

April 7, 1977

This approval is based upon the necessity of the septic tank and drain-field systems being located by the Mecklenburg County Health Department by permit. Therefore, we recommend that each buyer contact this office before any construction is started.

Also, local ordinance requires that a building permit be obtained from the Mecklenburg County Building Inspector, Boydton, Virginia, before construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

c.c.: Mr. B. D. McCauley, Mecklenburg County Administrator

MECKLENBURG COUNTY HEALTH DEPARTMENT  
BOYDTON, VIRGINIA 23917

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

June 27, 1977

Mr. David Wilson, President  
Merifield Acres, Inc.  
Clarksville, Virginia 23927

Dear Mr. Wilson:

On June 27, 1977 a soil evaluation of Merifield Acres, Unit 8, Section A was completed by Wayne Lenhart, Sanitarian, and myself.

Lots 1, 2, 3, 4, 5, 6, 7, 8, 10, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 39, 40, 41, 42, 43, 44, and 47 are considered to be suitable for the installation of septic tank and drainfield systems for single family dwelling unit with an individual water supply per lot.

Due to unfavorable soil characteristics and position in the landscape, Lots 9, 11, 24, 25, 36, 37, 38, 45, and 46 are not considered suitable for the installation of drainfield systems.

Also, it should be noted that, depending on house location, some systems may require pumping of the effluent from the septic tank to the drainfield.

This approval is based upon the necessity of the septic tank and drainfield being properly located by the Mecklenburg County Health Department. Therefore, we recommend that each buyer contact this office before any construction is started.

Local ordinance requires that a building permit be obtained from the Office of the Building Inspector, Boydton, Virginia, before any construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:jab  
c.c.: Mr. B. D. McCauley, Mecklenburg County Administrator

MECKLENBURG COUNTY HEALTH DEPARTMENT

BOYDTON, VIRGINIA

July 29, 1977

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Clarksville, Virginia 23927

Dear Mr. Wilson:

On July 28, 1977, a soil evaluation of Unit 8, Section B, Merifield Acres, was completed by Wayne Lenhart, Sanitarian, Mecklenburg County Health Department, and me.

Lots 48, 49, 50, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 75, 78, 79, 80, 81, 82, 84, 85, 86, 87, 88, 89, and 90 are considered suitable for a septic tank and drainfield system for individual dwelling units (up to three (3) bedrooms) with an individual water supply for each lot.

Lots 62, 74, and 77 are considered suitable for drainfield systems for individual dwelling units with a maximum of two (2) bedrooms.

Due to the position in the landscape and unacceptable soil characteristics, lots 51, 76, and 83 are not considered suitable for the installation of drainfield type sewage disposal systems.

It should be noted that, depending on house location, some lots may require a pumping system to get the effluent from the septic tank to the drainfield area.

This approval is based on the necessity of the septic tank and drainfield systems being properly located by the Mecklenburg County Health Department. Therefore, we recommend that each buyer contact this office before any construction is started.

Also, local ordinance requires that a Building Permit be obtained from the Office of the Building Inspector, Mecklenburg County, Boynton, Virginia, before any construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

c.c.: Mr. B. D. McCauley

MECKLENBURG COUNTY HEALTH DEPARTMENT  
BOYDTON, VIRGINIA 23917

November 10, 1977

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

TELEPHONE 738-0545

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Clarksville, Virginia 23927

Dear Mr. Wilson:

On November 10, 1977, a soil evaluation of Unit 8, Section D, Merifield Acres, was completed by Wayne Lenhart, Sanitarian, and me.

Lots 125, 126, 127, 134, 135, 137, 138, 139, 140, 143, 144, and 145 are considered suitable for the installation of septic tank and drainfield systems for single family dwelling units (up to three bedrooms) with an individual water supply per lot.

Lot 136 is suitable for a single family dwelling unit of no more than two bedrooms.

Due to unsuitable soil characteristics and the position in the landscape, lots 128, 129, 130, 131, 132, 133, 141, 142, 146, and 147 are not considered suitable for the installation of drainfield systems.

It should be noted that, depending on the house location, some lots may require a pumping system to get the effluent from the septic tank to the drainfield.

This approval is based upon the necessity of the septic tank and drainfield systems being properly located by the Mecklenburg County Health Department. Therefore, we recommend that each buyer contact this office before any construction is started.

Local ordinance requires that a Building Permit be obtained from the Mecklenburg County Building Inspector, Boydton, Virginia, before construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

c.c.: Mr. B. D. McCauley, Mecklenburg County Administrator

MECKLENBURG COUNTY HEALTH DEPARTMENT  
BOYDTON, VIRGINIA 23917

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

September 29, 1977

TELEPHONE: 738-6545

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Rt. 1, Box 60  
Clarksville, Virginia 23927

Dear Mr. Wilson:

A soil evaluation of Unit 8, Section E, Merifield Acres, was completed by Wayne Lenhart, Sanitarian, Mecklenburg County Health Department, and me.

Lots 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, and 175 are considered suitable for the installation of a septic tank and drainfield system for individual dwelling units (up to three (3) bedrooms) with an individual water supply for each lot.

It should be noted that, depending on house location, some lots may require a pumping system to get the effluent from the septic tank to the drainfield area.

This approval is based on the necessity of the septic tank and drainfield systems being properly located by the Mecklenburg County Health Department. Therefore, we recommend that each buyer contact this office before any construction is started.

Also, local ordinance requires that a Building Permit be obtained from the Office of the Building Inspector, Mecklenburg County, Boydton, Virginia, before any construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:rw

c.c.: Mr. B. D. McCauley

MECKLENBURG COUNTY HEALTH DEPARTMENT

BOYDTON, VIRGINIA 23917

April 7, 1978

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

Mr. David Wilson  
Merifield Acres, Incorporated  
Clarksville, Virginia 23927

Dear Mr. Wilson:

On April 5, 1978, a soil evaluation of Merifield Acres, Unit 9, Section A, was completed by Wayne Lenhart, Sanitarian, and me.

Based on a revised plat submitted on April 7, 1978, the results of our evaluation are as follows:

Lots 1, 2, 7, 8, 9, 10, 11, 12, 18, 19, 23, 24, 25, 26, 27, 30, 31, 32, 33, 34, 35, 36, 44, 45, 48, 74, 75, 76, 77, 78, 80, 81, 82, 83, 84, 85, 87, 89, 91, 92, 93, 94, and 95 are considered suitable for the installation of septic tank and sub-surface drainfield systems for individual dwelling units (up to three (3) bedrooms) with an individual water supply. Lot 43 is also approved in this group.

Lots 4, 17, 20, 28, 39, 40, 41, 47, 49, 50, and 86 are considered suitable for the installation of septic tank and sub-surface drainfield systems for individual dwelling units of no more than two (2) bedrooms, with an individual water supply.


Lots 3, 5, 6, 13, 14, 15, 16, 21, 22, 29, 37, 38, 42, 46, 51, 79, 88, and 90 are not considered suitable for the installation of sub-surface drainfield systems.

Depending on the house location, some lots may require that a pumping system be installed to get the effluent from the septic tank to the drainfield. Also, on certain lots, the home owner must assume all liability relating to the excessive depth of the drainfield system.

This approval is based upon the necessity of the drainfield system being properly located by the Mecklenburg County Health Department; therefore, we recommend that each buyer contact this office before any construction is started.

Local ordinance requires that a building permit be obtained from the Office of the Building Inspectors, Boydton, Virginia, before any construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

MECKLENBURG COUNTY HEALTH DEPARTMENT  
BOYDTON, VIRGINIA 23917

April 7, 1978

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

*noted*

Mr. David Wilson  
Merifield Acres, Incorporated  
Clarksville, Virginia 23927

Dear Mr. Wilson:

On April 5, 1978, a soil evaluation of Merifield Acres, Unit 9, Section A, was completed by Wayne Lenhart, Sanitarian, and me.

Based on a revised plat submitted on April 7, 1978, the results of our evaluation are as follows:

Lots 1, 2, 7, 8, 9, 10, 11, 12, 18, 19, 23, 24, 25, 26, 27, 30, 31, 32, 33, 34, 35, 36, 44, 45, 48, 74, 75, 76, 77, 78, 80, 81, 82, 83, 84, 85, 87, 89, 91, 92, 93, 94, and 95 are considered suitable for the installation of septic tank and sub-surface drainfield systems for individual dwelling units (up to three (3) bedrooms) with an individual water supply. Lot 43 is also approved in this group.

Lots 4, 17, 20, 28, 39, 40, 41, 47, 49, 50, and 86 are considered suitable for the installation of septic tank and sub-surface drainfield systems for individual dwelling units of no more than two (2) bedrooms, with an individual water supply.


Lots 3, 5, 6, 13, 14, 15, 16, 21, 22, 29, 37, 38, 42, 46, 51, 79, 88, and 90 are not considered suitable for the installation of sub-surface drainfield systems.

Depending on the house location, some lots may require that a pumping system be installed to get the effluent from the septic tank to the drainfield. Also, on certain lots, the home owner must assume all liability relating to the excessive depth of the drainfield system.

This approval is based upon the necessity of the drainfield system being properly located by the Mecklenburg County Health Department; therefore, we recommend that each buyer contact this office before any construction is started.

Local ordinance requires that a building permit be obtained from the Office of the Building Inspectors, Boydton, Virginia, before any construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

MECKLENBURG COUNTY HEALTH DEPARTMENT  
BOYDTON, VIRGINIA 23917

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

May 4, 1978

TELEPHONE: 736-6545

Mr. David Wilson  
Merifield Acres, Incorporated  
Rt. 1, Box 60  
Clarksville, Virginia 23927

Dear Mr. Wilson,

On May 3, 1978, a soil evaluation of Merifield Acres, Unit 9, Section B, was completed by Wayne Lenhart, Sanitarian, and me.

The results of our evaluation are as follows:

Lots 52, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 101, 102, 103, 104, 108, 109, 110, 111, 114, 115, 116, 117, 118, 119, and 120, are considered suitable for the installation of septic tank and sub-surface drainfield systems for single family dwelling units (up to three (3) bedrooms) with an individual water supply.

Lots 55, 73, 96, 97, 98, 99, 105, 106, 107, 112, 113, and 121 are considered suitable for drainfield systems for single family dwelling units of no more than two (2) bedrooms with an individual water supply.

Lot 100 is to be reserved as well location for the proposed campground; therefore, no sewage system will be allowed on this lot.

Due to unfavorable soil conditions, lots 53 and 54 are not considered suitable for drainfield type sewage disposal systems.

Also, it should be noted that, depending on house location, some lots may require a pumping system to get the effluent from the septic tank to the drainfield.

This approval is based upon the necessity of the drainfield system being properly located by the Mecklenburg County Health Department; therefore, we recommend that each buyer contact this office before any construction is started.

Local ordinance requires that a building permit be obtained from the office of the Building Inspectors, Boydton, Virginia, before any construction is started.

Sincerely yours,

*L. J. Hite*

L. J. Hite  
Sanitation Supervisor

LJH:bb

cc: Mr. B. E. McCauley

MECKLENBURG COUNTY HEALTH DEPARTMENT

BOYDTON, VIRGINIA 23917

May 30, 1978

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

TELEPHONE: 738-6545

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Route 1, Box 60  
Clarksville, Virginia 23927

Dear Mr. Wilson:

A soil evaluation of Merifield Acres, Unit 9, Section C, has been completed by the Mecklenburg County Health Department. The results of our evaluation are as follows:

Lots 122, 123, 124, 125, 128, 129, 130, 131, 135, 136, 137, 138, 139, 141, 142, 143, 149, 150, 151, 152, 153, 154, 155, 159, 160, 161, 162, 163, 164, 165, 166, and 167 are considered suitable for the installation of septic tank and drainfield systems for individual dwelling units (up to three bedrooms) with an individual water supply per lot.

Lots 132, 133, 134, 144, 145, 146, 147, and 148 are suitable for drainfield type systems for dwelling units of no more than two bedrooms.


Due to the position in the landscape and unacceptable soil characteristics, lots 126, 127, 140, 156, 157, and 158 are not considered suitable for septic tank and drainfield sewage disposal systems.

It should be noted that, depending on house location, some lots may require that a pumping system be installed to get the sewage effluent from the septic tank to the drainfield.

Approval of these lots is based upon the necessity of the septic tank and drainfield systems being properly located by the Mecklenburg County Health Department. Therefore, we recommend that each buyer contact this office before any construction is started.

Also, local ordinance requires that a Building Permit be obtained from the Office of Building Inspectors, Mecklenburg County, Boydton, Virginia, before any construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

c.c.: Mr. B. D. McCauley, Mecklenburg County Administrator

MECKLENBURG COUNTY HEALTH DEPARTMENT

BOYDTON, VIRGINIA 23917

May 30, 1978

IN COOPERATION WITH THE  
STATE DEPARTMENT OF HEALTH

TELEPHONE: 738-6545

Mr. David Wilson, President  
Merifield Acres, Incorporated  
Route 1, Box 60  
Clarksville, Virginia 23927

*noted*

Dear Mr. Wilson:

A soil evaluation of Merifield Acres, Unit 9, Section C, has been completed by the Mecklenburg County Health Department. The results of our evaluation are as follows:

Lots 122, 123, 124, 125, 128, 129, 130, 131, 135, 136, 137, 138, 139, 141, 142, 143, 149, 150, 151, 152, 153, 154, 155, 159, 160, 161, 162, 163, 164, 165, 166, and 167 are considered suitable for the installation of septic tank and drainfield systems for individual dwelling units (up to three bedrooms) with an individual water supply per lot.

Lots 132, 133, 134, 144, 145, 146, 147, and 148 are suitable for drainfield type systems for dwelling units of no more than two bedrooms.

Due to the position in the landscape and unacceptable soil characteristics, lots 126, 127, 140, 156, 157, and 158 are not considered suitable for septic tank and drainfield sewage disposal systems.

It should be noted that, depending on house location, some lots may require that a pumping system be installed to get the sewage effluent from the septic tank to the drainfield.

Approval of these lots is based upon the necessity of the septic tank and drainfield systems being properly located by the Mecklenburg County Health Department. Therefore, we recommend that each buyer contact this office before any construction is started.

Also, local ordinance requires that a Building Permit be obtained from the Office of Building Inspectors, Mecklenburg County, Boydton, Virginia, before any construction is started.

Sincerely yours,



L. J. Hite  
Sanitation Supervisor

LJH:pp

c.c.: Mr. B. D. McCauley, Mecklenburg County Administrator

Information by Mr. ~~Wesley~~ Lenthart, 6/20/78

Unit  
3

Lat (30 + 31) + 18 No Perk  
No Inf.

19, 20, 21, 24, 26, 32, 33, 34

4

40 No Inf. perks

55 No Perk

49 no "

54 " Perk

{ 53 (portion)  
56 Not Suit no perk

57, 58, 61, 62

5

26 No Perk

3, 4, 8, 20, 29, 35, 36, 16